

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 44400	Mair Ota		0	Otro at				Location:	N
Intersection ID: 14468	wain Str	Main Street: E_TREMONT_AV			Cross Street: EUCLID_AV				N
ADA ID: 8DA0D82E1834	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
	ANY AN	Remove & Replace Entire Rai	np.	N/A	Ramp Length (in)	76.0	N/A	Grade Break?	N/A
		-	•	Yes	Ramp Width (in)	70.0	N/A	Grade Break Slope (%)	0.0
				Yes	Ramp Slope (%)	2.2	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	2.9			
A A A A A A A A A A A A A A A A A A A	11/1/2/2			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
The last				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
<u>स</u> ह 🏈	155	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
North Real				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
LAND B. KON	5.			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
134 133	Contraction of the second	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	5 3 4			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	KIL M			N/A	Painted X Walk1?	No		Road Slope (%)	3.5
Street 1 Name	E TREMONT AV				X Walk 1 Direction	To SW		Road X Slope (%)	3.1
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	3.5	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	3.1	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	10.5

