cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 30291	Main Str	Main Street: BLYTHEDALE_DR Cro			GALLATIN_LN	Location:	S		
ADA ID: 8DCB8347CA8E	Ramp Type: Perpendicular Diagonal Initia			I Pass/Fail: Pass Overall Compliance: No				o Severity Score:	29.25
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
	CILLATING LAS	Possible Solutions:		Compliance Description		Data Compliance Description		Data	
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	/ith	N/A	Ramp Length (in)	46.0	Yes	Ramp Slope (%)	5.6
				Yes	Ramp Width (in)	64.0	No	Ramp XSlope (%)	2.2
				N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	2.4	N/A	Flare Slope RT (%)	4.4
				N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
				No	Landing Length (in)	47.0	No	DWS Provided?	No
		Surveyor Notes:		No	Landing Width (in)	39.0	N/A	DWS Contrast?	No
		N/A		No	Landing Slope (%)	4.1	N/A	DWS Length (in)	N/A
				No	Landing X Slope (%)	3.3	N/A	DWS Full Width?	No
				N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	No			
APP II Para		PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.4
		Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R305, R302.7.2		No	Gutter Lip Ht (in)	1.0	Yes	Gutter X Slope (%)	0.5
			05,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To E		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	GALLATIN LN				X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	1.2
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	0.9
Street 2 Name	BLYTHEDALE DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	1.9	N/A	Clear Space?	Yes
					Road X Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

