

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 23558Main Street: HAMLIN_PARK_DRCross Street: PARK_RDLocation:NEADA ID: 8E03B05A0FA2Ramp Type: ParaInitial Pass/Fail: FailOverall Compliance: NoSeverity Score: 13.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name PARK RD
Stop Condition-Street 1 None
Street 2 Name N/A
Stop Condition-Street 2 N/A

1 033IDIC OCIULIOII	
Possible Solutions:	C
Remove & Replace Entire Ramp.	N
	Ye
	N
	N
	N/
	N/
Surveyor Notes:	N/
N/A	N/
	N/
	N/
	N/
PROW/ADA:	N/
R304.3.2, R304.5.3	N/
	N/

Total Cost: \$ 1600.00

Compliance Description Data Compliance Description Data						
		Data		Description	Data	
N/A	Ramp Length LT (in)	71.0	N/A	Ramp Length RT (in)	72.0	
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0	
No	Ramp Slope LT (%)	9.0	Yes	Ramp Slope RT (%)	5.3	
No	Ramp XSlope LT (%)	2.4	No	Ramp XSlope RT (%)	2.4	
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
	X Walk 1 Slope (%)	5.6		X Walk 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	0.8		X Walk 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
	,,	N/A		, ,,	N/A	
			Yes	Surface Condition? (G/P)	Good	
			N/A	Curb Slope (%)	16.3	
	A STATE OF THE STA					
- ma	A SECURITY OF THE PARTY OF THE					





