## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51046	tion ID: 51046 Main Street: LONGNOR_ST			Cross Street: PALATINE_LN				Location:	NE
ADA ID: 8EBC02AEAE8D	BD Ramp Type: BlendTrans1			itial Pass/Fail: Pass Overall Compliance: No				Severity Score:	5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Curb Ramp	With	N/A	Ramp Length (in)	95.0	Yes	BlendTrans Slope (%)	5.0
		Two New Directional Ramps or		Yes	Ramp Width (in)	60.0	Yes	BlendTrans XSlope (%)	1.7
		Equivalent. Remove & Replace		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
		Gutter.		Yes	Flare Slope LT (%)	7.0	Yes	Flare Slope RT (%)	4.0
				N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
	- 1 1			Yes	Landing Length (in)	60.5	Yes	DWS Provided?	Yes
		Surveyor Notes:		Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
		N/A		No	Landing Slope (%)	2.3	Yes	DWS Length (in)	24.0
RALATIN				No	Landing X Slope (%)	2.2	Yes	DWS Full Width?	Yes
E PALATINE LM				N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	5.0
	A ANTENNA AN			N/A	Shared Landing?	No			
	Banks 14	PROW/ADA:		No	Gutter Ponding?	Yes	No	Gutter Slope (%)	9.5
	T	Not Found, R304.2.2-Perp, R30	.3.2-	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.5
		Para, R304.5.3, R305.2, R302.7,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		R304.5.4			X Walk 1 Direction	To W		X Walk 2 Direction	To S
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	LONGNOR ST				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	1.7
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	0.1
Street 2 Name	PALATINE LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	StopSign				Road Slope (%)	1.4		Clear Space?	Yes
					Road X Slope (%)	1.4	N/A	Clear Space to XWalk (in)	N/A
				Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
		Total Cost: \$ 3	3950.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good







No

Curb Slope (%)

11.5