

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10642 Main Street: HOBBS\_ST Cross Street: SYLVANIA\_AV Location: N

ADA ID: 8EE3712EEA1E Ramp Type: Perpendicular Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name HOBBS ST
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3

Total Cost: \$ 1850.00

| Field Measurements/Component Compliance |  |       |      |                             |      |
|---|--|-------|------|-----------------------------|------|
| Compliance Description                  |  | Data  | Comp | oliance Description         | Data |
| N/A                                     | Ramp Length (in)   | 61.5  | Yes  | Ramp Slope (%)              | 6.0  |
| Yes                                     | Ramp Width (in)  | 48.0  | No   | Ramp XSlope (%)             | 2.7  |
| N/A                                     | Flare Type LT  | N/A   | N/A  | Flare Type RT               | N/A  |
| N/A                                     | Flare Slope LT (%)   | N/A   | N/A  | Flare Slope RT (%)          | N/A  |
| N/A                                     | Flare Traversable LT?  | N/A   | N/A  | Flare Traversable RT?       | N/A  |
| N/A                                     | Landing Length (in)  | N/A   | N/A  | DWS Provided?               | N/A  |
| N/A                                     | Landing Width (in)   | N/A   | N/A  | DWS Contrast?               | N/A  |
| N/A                                     | Landing Slope (%)  | N/A   | N/A  | DWS Length (in)             | N/A  |
| N/A                                     | Landing X Slope (%)  | N/A   | N/A  | DWS Full Width?             | N/A  |
| N/A                                     | Landing Curb? (Y/N)  | N/A   | N/A  | DWS Offset (in)             | N/A  |
| N/A                                     | Shared Landing?  | N/A   |      |                             |      |
| N/A                                     | Gutter Ponding?  | N/A   | N/A  | Gutter Slope (%)            | N/A  |
| N/A                                     | Gutter Lip Ht (in)   | 1.0   | N/A  | Gutter X Slope (%)          | N/A  |
| N/A                                     | Painted X Walk1?   | No    | N/A  | Painted X Walk2?            | N/A  |
|   | X Walk 1 Direction   | To SE |      | X Walk 2 Direction          | N/A  |
| N/A                                     | X Walk 1 Width (in)  | N/A   | N/A  | X Walk 2 Width (in)         | N/A  |
|   | X Walk 1 Slope (%)   | 2.3   |      | X Walk 2 Slope (%)          | N/A  |
|   | X Walk 1 X Slope (%)   | 0.9   |      | X Walk 2 X Slope (%)        | N/A  |
| N/A                                     | Ramp inside XWalk1?  | N/A   | N/A  | Ramp inside XWalk2?         | N/A  |
|   | Road Slope (%)   | N/A   | N/A  | Clear Space?                | N/A  |
|   | Road X Slope (%)   | N/A   | N/A  | Clear Space to XWalk (in)   | N/A  |
| N/A                                     | Any Obstructions?  | N/A   | N/A  | Storm Grate/Utility Hazard? | N/A  |
|   | Obstruction Type   |       |      | Storm Grate/Utility Type    |      |
|   |  | N/A   |      |                             | N/A  |
|   |  |       | Yes  | Surface Condition? (G/P)    | Good |
| · Mar                                   | The state of the s |       | •    | , ,                         |      |





