

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 12157 Main	Main Street: MIDLAND_AV			AMERIGO_ST	Location:	W		
	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: N			nce: No		10
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Co	Compliance Description Data			Compliance Description Date		Data
	Remove & Replace Entire Ramp	. N/.	Α	Ramp Length (in)	52.0	Yes	Ramp Slope (%)	6.4
2		No	0	Ramp Width (in)	47.5	No	Ramp XSlope (%)	3.9
		N/	A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/.	Α	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
6.		N/.	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/.	Α	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/.	Α	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/.	Α	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/.	Α	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	The second second	N/.	Α	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/.	Α	Shared Landing?	N/A			
The second second	PROW/ADA:	N/.	Α	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3	N/.	A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	75	N/.	Α	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A
	- A	N/.	Α	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name AMERIGO	ST			X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 StopS	gn			X Walk 1 X Slope (%)	3.6		X Walk 2 X Slope (%)	N/A
Street 2 Name	//A	N/.	Α	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	I/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
				•••	N/A			N/A

