

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6463Main Street:ROSY\_MOUND\_LNCross Street:SLATER\_SPRINGS\_DRLocation:NWADA ID: 9122501EC92ARamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name ROSY MOUND LN
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Total Cost: \$ 1850.00

| Compliance Description Da |                       | Data  | Compliance Description |                             | Data |
|---------------------------|-----------------------|-------|------------------------|-----------------------------|------|
| N/A                       | Ramp Length (in)      | 90.0  | No                     | Ramp Slope (%)              | 9.0  |
| Yes                       | Ramp Width (in)       | 48.0  | Yes                    | Ramp XSlope (%)             | 0.9  |
| N/A                       | Flare Type LT         | N/A   | N/A                    | Flare Type RT               | N/A  |
| N/A                       | Flare Slope LT (%)    | N/A   | N/A                    | Flare Slope RT (%)          | N/A  |
| N/A                       | Flare Traversable LT? | N/A   | N/A                    | Flare Traversable RT?       | N/A  |
| N/A                       | Landing Length (in)   | N/A   | N/A                    | DWS Provided?               | N/A  |
| N/A                       | Landing Width (in)    | N/A   | N/A                    | DWS Contrast?               | N/A  |
| N/A                       | Landing Slope (%)     | N/A   | N/A                    | DWS Length (in)             | N/A  |
| N/A                       | Landing X Slope (%)   | N/A   | N/A                    | DWS Full Width?             | N/A  |
| N/A                       | Landing Curb? (Y/N)   | N/A   | N/A                    | DWS Offset (in)             | N/A  |
| N/A                       | Shared Landing?       | N/A   |                        |                             |      |
| N/A                       | Gutter Ponding?       | N/A   | N/A                    | Gutter Slope (%)            | N/A  |
| N/A                       | Gutter Lip Ht (in)    | N/A   | N/A                    | Gutter X Slope (%)          | N/A  |
| N/A                       | Painted X Walk1?      | No    | N/A                    | Painted X Walk2?            | N/A  |
|                           | X Walk 1 Direction    | To NE |                        | X Walk 2 Direction          | N/A  |
| N/A                       | X Walk 1 Width (in)   | N/A   | N/A                    | X Walk 2 Width (in)         | N/A  |
|                           | X Walk 1 Slope (%)    | 0.1   |                        | X Walk 2 Slope (%)          | N/A  |
|                           | X Walk 1 X Slope (%)  | 2.1   |                        | X Walk 2 X Slope (%)        | N/A  |
| N/A                       | Ramp inside XWalk1?   | N/A   | N/A                    | Ramp inside XWalk2?         | N/A  |
|                           | Road Slope (%)        | N/A   | N/A                    | Clear Space?                | N/A  |
|                           | Road X Slope (%)      | N/A   | N/A                    | Clear Space to XWalk (in)   | N/A  |
| N/A                       | Any Obstructions?     | N/A   | N/A                    | Storm Grate/Utility Hazard? | N/A  |
|                           | Obstruction Type      |       |                        | Storm Grate/Utility Type    |      |
|                           |                       | N/A   |                        |                             | N/A  |
|                           |                       |       | Yes                    | Surface Condition? (G/P)    | Good |
|                           |                       |       |                        |                             |      |





