cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50589	Main Stre	Main Street: BENDING_BRANCH_RD			GREEN_GRASS_RD	Location:	S			
ADA ID: 92339C22A6F6	Ramp Typ	Ramp Type: BlendTrans1			itial Pass/Fail: Fail Overall Compliance:			o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	Possible Solutions:					liance Description	Data			
	1/10	Remove & Replace Curb R	ome With	N/A	Ramp Length (in)	48.0		BlendTrans Slope (%)	3.9	
	1 11-	Two New Directional Ramp	•	No	Ramp Width (in)	47.5		BlendTrans XSlope (%)	3.3 1.2	
	N.DA	Equivalent.		N/A	Flare Type LT	47.5 N/A		Flare Type RT	N/A	
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A	
					Flare Traversable LT?			Flare Traversable RT?		
				N/A		N/A			N/A	
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A	
	453	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	1 AMASING	N/A		N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A	
	1 AD			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	A ST OK			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	N & Store	Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	B 100 27			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	1010				X Walk 1 Direction	To NW		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name BENDING BRANCH RD				X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A		
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	2.3		Clear Space?	N/A	
					Road X Slope (%)	1.4		Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A		cloth craterounty type	N/A	
						IN/A	1		11/17	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.5