

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18036	Main Street: INWOOD_DR		Cross Street: SOUTH_BV					Location:	NW
ADA ID: 92BD1ACFD54A	Ramp Type: PerpDiag		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:						liance Description	Data
	E	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	57.0	No	Ramp Slope (%)	8.5
		Two New Directional Ramps or		Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	1.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		-		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	B INVOOD DR			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A		Divo Oliser (III)	17.5
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A A A A A A A A A A A A A A A A A A A	Le. V				-		N/A		
the state of the s	1 Ale	Not Found, R304.2.2		N/A N/A	Gutter Lip Ht (in) Painted X Walk1?	N/A	N/A N/A	Gutter X Slope (%) Painted X Walk2?	N/A
	I G			N/A		No Tu O	N/A		No Ta F
					X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	INWOOD DR				X Walk 1 Slope (%)	5.5		X Walk 2 Slope (%)	6.9
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	4.5		X Walk 2 X Slope (%)	0.2
Street 2 Name	SOUTH BV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	2.3	N/A	Clear Space?	N/A
					Road X Slope (%)	7.2	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good



