

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11695 Main Street: PARKWOOD_AV Cross Street: THE_PLAZA							Location:	NW	
ADA ID: 930BFA1D019D	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No					12.5
· · ·			iiiitiai						12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	THE SLEEP	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
		Remove & Replace Curb Ramp		N/A	Ramp Length (in)	40.5	Yes	BlendTrans Slope (%)	0.8
		Two New Directional Ramps of	r	Yes	Ramp Width (in)	60.0	No	BlendTrans XSlope (%)	5.4
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
the second second				N/A	Shared Landing?	N/A			
Ep-0-6		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
A GOOD				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
PARKINGOLS	A stalla				X Walk 1 Direction	To S		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	LOLA AV	-			X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				, Road Slope (%)	1.1		Clear Space?	N/A
					Road X Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		······ •				N/A			N/A
						1.7	1		10/5







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

13.4