

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13196	: 13196 Main Street: ELIZABETH_AV					N_LONG_ST	Location:	Е		
ADA ID: 935FEE4C3D84	Ramp Type: BlendTrans1				Initial Pass/Fail: Fail Overall Compliance: No					
				minia	1 433/1 6			21.25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	SEC ET THE THE THE	Possible Solutions:			Comp	Compliance Description			liance Description	Data
1.0125		Remove & Replace Cu	-		N/A	Ramp Length (in)	83.0	Yes	BlendTrans Slope (%)	2.0
		Two New Directional Equivalent.			No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	5.7
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	17				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	61	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	11.5	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	all Are				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
E B				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
a forth and		Not Found, R304.5.1, R304.5.3		3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,, -		-	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
						X Walk 1 Direction	To NW		X Walk 2 Direction	To SW
un a B					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name	N LONG ST					X Walk 1 Slope (%)	3.5		X Walk 2 Slope (%)	2.5
Stop Condition-Street 1	StopSign					X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	2.9
Street 2 Name	LIZABETH AV				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None					Road Slope (%)	3.2		Clear Space?	N/A
						Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A		5 51	N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

5.4