## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14326	Main Street: BALDWIN_AV		Cross	Cross Street: LUTHER_ST			Location:	Ν	
ADA ID: 947D77EC52BD	Ramp Type: PerpDiag		Initial	Initial Pass/Fail: Fail Overal		II Compliance: No		o Severity Score:	46.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
No States Alexander	Possible S	Possible Solutions:		Compliance Description		Data	Comp	liance Description	Data
A A A	Remov	ve & Replace Curb Ramp	With	N/A	Ramp Length (in)	33.5	No	Ramp Slope (%)	9.6
		lew Directional Ramps or		No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	7.4
	Equiva	Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	11 5			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	A CAL	8		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
States States	Surveyor	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E ST	N/A	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
- Starts	All for			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Start 1			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
B.B.	141.15			N/A	Shared Landing?	N/A			
	PROW/AI	PROW/ADA: Not Found, R304.5.1, R304.2.2,		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
and the second second	Not Fo			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	No. of Concession, Name of	R304.5.3	,	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
× / K. //	A CONTRACTOR				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
1 and the second	2.10			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name LU	THER ST				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	4.5
	StopSign				X Walk 1 X Slope (%)	6.7		X Walk 2 X Slope (%)	2.5
•	DWIN AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	7.3	N/A	Clear Space?	N/A
					Road X Slope (%)	3.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
	Total Cos	st: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good



