

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6379Main Street: COLLINS\_STCross Street: LAKE\_RDLocation:SEADA ID: 9603466E57D4Ramp Type: PerpInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name

COLLINS ST
Stop Condition-Street 2

None
Street 2 Name

N/A
Stop Condition-Street 1

N/A

Possible Solutions:	
Remove & Replace Entire Ramp.	
Company Notes	
Surveyor Notes:	
N/A	
PROW/ADA:	
Not Found, R304.5.1, R304.2.2	
, , , ,	





Total Cost:



1850.00

- a55/F	all. Fall Overall	Compilar	ice. N	o Severity Score.	22.		
Field Measurements/Component Compliance							
Comp	liance Description	Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	8.9		
No	Ramp Width (in)	47.5	Yes	Ramp XSlope (%)	2.6		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type		l	Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		