

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



									I	
Intersection ID: 7724	Main Street: BEATTIES_FORD_RD			treet:	N_I-85_EXIT_37_RA			Location:	NW	
ADA ID: 967E65E6BA3C	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	CONTRACTOR OF A	Possible Solutions:					Compliance Description		Data	
1 1000		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	68.0	Yes	Ramp Slope (%)	6.8	
			•	No	Ramp Width (in)	46.5	No	Ramp XSlope (%)	4.3	
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	1 . 1997			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
tes he :				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A AND AND A		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
日本的人口				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
TIL ST.	Level 1			N/A	Shared Landing?	N/A		( )		
MARIE ECHAN	- I Martin	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
The state of the	1 c 1 6	R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
The second se	6	1004.0.1, 1004.0.0		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
	5 TIME				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
A Star da Mar			N/A	X Walk 1 Width (in)	110.5	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	N I-85 EXIT 37 RA				X Walk 1 Slope (%)	6.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
		······ • • • • • •				N/A			N/A	
						1.74			11/2	

Yes Surface Condition? (G/P)

Good

