cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 51310	Main Street: I-485 RA		Cross Street: W_W_T_HARRIS_BV				Location: E		
ADA ID: 968ECAE9E399	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data Compliance Description Data					
E E		4	A/:41a	N/A	Ramp Length (in)	59.0	Yes	BlendTrans Slope (%)	2.1
		Remove & Replace Curb Ramp V Two New Directional Ramps or	vitn	No	Ramp Width (in)	46.0	Yes	BlendTrans XSlope (%)	0.6
		Equivalent.		N/A	,	40.0 N/A	N/A		0.8 N/A
		Equivalent			Flare Type LT			Flare Type RT	
				N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	113.0		X Walk 2 Width (in)	N/A
Street 1 Name	I-485 RA	-			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	Signal				X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	2.3		Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	0.7 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00	11/7	Obstruction Type	17/4		Storm Grate/Utility Type	17/5
			200.00			N1/A		Storm Grate/Otility Type	N/A
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.8