## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16905		Cross	troot		Location	N		
	Main Street: BILTMORE_DR		Cross Street: SCOTLAND_AV				Location:	N
ADA ID: 96D7ECB7E88D Ramp T	Ramp Type: BlendTrans2		nitial Pass/Fail: Pass Overall Compliance: N			nce: N	o Severity Score:	0.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
CE SCOLLAR	Possible Solutions: Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		Compliance Description		Data Comp		liance Description	Data
		With	N/A	Ramp Length (in)	135.0	Yes	BlendTrans Slope (%)	3.5
			Yes	Ramp Width (in)	50.0	No	BlendTrans XSlope (%)	2.6
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			N/A	Landing Length (in)	N/A	Yes	DWS Provided?	Yes
	Surveyor Notes:		N/A	Landing Width (in)	N/A	Yes	DWS Contrast?	Yes
	N/A		N/A	Landing Slope (%)	N/A	Yes	DWS Length (in)	24.0
			N/A	Landing X Slope (%)	N/A	Yes	DWS Full Width?	Yes
			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0
L.			N/A	Shared Landing?	No			
	PROW/ADA:		Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	0.6
	Not Found, R304.5.3, R305.2		Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	3.4
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To SW		X Walk 2 Direction	To SE
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name BILTMORE DR	-			X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	2.0
Stop Condition-Street 1 StopSign				X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	1.4
Street 2 Name SCOTLAND AV			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2 None				, Road Slope (%)	2.1		Clear Space?	Yes
				Road X Slope (%)	0.3	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Total Cost: \$ 3	950.00		Obstruction Type			Storm Grate/Utility Type	-
	•			<i>,</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

12.7