## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52600 Main St	Main Street: MCCULLOUGH_DR			IKEA_BV	Location:	SW			
ADA ID: 9795823BD18C Ramp T	Ramp Type: Perp			il: Pass Overall	o Severity Score:	0.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance							
	Possible Solutions:	Compliance Description			Data	Data Compliance Description			
	Remove & Replace Entire Ramp Remove & Replace Gutter.		N/A	Ramp Length (in)	71.5	Yes	Ramp Slope (%)	6.8	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.6	
		1	N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A	
		1	N/A	Flare Slope LT (%)	6.6	N/A	Flare Slope RT (%)	9.9	
		I	N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No	
		Y	Yes	Landing Length (in)	72.0	Yes	DWS Provided?	Yes	
	Surveyor Notes:	Y	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
	N/A	Y	Yes	Landing Slope (%)	2.0	Yes	DWS Length (in)	24.0	
		1	No	Landing X Slope (%)	4.3	Yes	DWS Full Width?	Yes	
		I	N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	1.5	
		I	N/A	Shared Landing?	No				
	PROW/ADA:	Y	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.5	
Ser 1 1 hours and the	Not Found, R304.5.3	١	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	2.6	
		1	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
A A A A A A A A A A A A A A A A A A A				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
		1	N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name IKEA BV	-			X Walk 1 Slope (%)	2.4		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2 None				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		Y	Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	Yes	
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		•	Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Total Cost: \$	600.00		Obstruction Type			Storm Grate/Utility Type		
				• •	N/A			N/A	

Yes Surface Condition? (G/P) Good

