

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10013090 Main Street: BELMONT_AV Cross Street: N/A Location: N

ADA ID: 97B3FE0EAD60 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



| | AND THE RESIDENCE OF THE PARTY |
|-------------------------|---|
| Street 1 Name | BELMONT AV |
| Stop Condition-Street 2 | None |
| Street 2 Name | N/A |
| Stop Condition-Street 1 | N/A |

| /Possible Solution | | | | |
|-------------------------------|--|--|--|--|
| Possible Solutions: | | | | |
| Remove & Replace Entire Ramp. | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Surveyor Notes: | | | | |
| N/A | | | | |
| | | | | |
| | | | | |
| DDOW/ADA | | | | |
| PROW/ADA: | | | | |
| R304.5.1 | | | | |
| | | | | |
| | | | | |
| ı | | | | |
| | | | | |
| | | | | |

| | N/A | |
|------|-------------|---------------|
| et 1 | N/A | |
| | | |
| | | |
| | Total Cost: | \$ 1850.00 |
| | | |

| Comp | liance Description | Data | | liance Description | Data |
|----------------|-----------------------|-------|-----|-----------------------------|------|
| N/A | Ramp Length (in) | 60.5 | Yes | Ramp Slope (%) | 6.4 |
| No | Ramp Width (in) | 47.0 | Yes | Ramp XSlope (%) | 1.3 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | 0.5 | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To S | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | 113.0 | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 1.3 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.5 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| Producting the | | | | | |





