cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 50709 Main S	reet: ARRIVAL_DR	Cross Street	Cross Street: BROTHERLY_LN				SW	
ADA ID: 97EA8ED39B30 Ramp	Type: BlendTrans1	Initial Pass/F	nitial Pass/Fail: Pass Overall Compliance: No			o Severity Score:	0.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Comp	Compliance Description Data		Compliance Description Data		Data	
	Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent. Remove & Replace Gutter.	/ith N/A	Ramp Length (in)	48.0	Yes	BlendTrans Slope (%)	4.2	
		Yes	Ramp Width (in)	48.0	Yes	BlendTrans XSlope (%)	4.0	
		N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped	
		Yes	Flare Slope LT (%)	6.0	N/A	Flare Slope RT (%)	2.5	
		N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	No	
		No	Landing Length (in)	47.0	Yes	DWS Provided?	Yes	
	Surveyor Notes:	Yes	Landing Width (in)	48.0	Yes	DWS Contrast?	Yes	
	,	Yes	Landing Slope (%)	1.8	Yes	DWS Length (in)	24.5	
	N/A	Yes	Landing X Slope (%)	4.1	Yes	DWS Full Width?	Yes	
		N/A	•••••	4.1 No	Yes	DWS Offset (in)	1.0	
		N/A N/A	Landing Curb? (Y/N) Shared Landing?	No	res	DWS Offset (III)	1.0	
			0	-	N.	0	4.0	
	PROW/ADA:	Yes	Gutter Ponding?	No	Yes	Gutter Slope (%)	1.2	
	Not Found, R304.2.1, R304.5.3	Yes	Gutter Lip Ht (in)	0.0	No	Gutter X Slope (%)	5.1	
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name BROTHERLY LN			X Walk 1 Slope (%)	4.1		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 None			X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 N/A			Road Slope (%)	4.9		Clear Space?	Yes	
			Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
	Total Cost: \$ 39	50.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.8