

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14318	Main Sti	Cross Str	Cross Street: WALLACE_AV					SE		
ADA ID: 98037515F0C0	Ramp T	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	22.5				
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description				Data Compliance Description		
1	1 BARA	Remove & Replace	Entiro Ramn	_		Ramp Length (in)	99.0	N/A	Grade Break?	Data N/A
	King and			N		Ramp Width (in)	46.0	N/A	Grade Break Slope (%)	0.0
and the second states of the	1 All month			N		Ramp Slope (%)	9.2	N/A	Grade Break XSlope (%)	0.0
	mont			N		Ramp XSlope (%)	3.8			
A CONTRACTOR OF THE OWNER	11 . 112	e M		N		Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N		Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
United States		Surveyor Notes:		N	Α	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A		N	Α	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
				N		Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
Contraction of the second seco	14/10			N		Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
13	14 Section			N		Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
142	2 ANN	PROW/ADA:		N		Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	and the second s	R304.5.1, R304.2.2,	R304 5 3	N		Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Che and	1,304.3.1, 1,304.2.2,	1.004.0.0	N		Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
The second	12 Martin			N		Gutter Lip Ht (in)	2.0	N/A	Gutter X Slope (%)	N/A
	all a m			N		Painted X Walk1?	No		Road Slope (%)	0.7
Street 1 Name	WALLACE AV	-				X Walk 1 Direction	To SW		Road X Slope (%)	8.5
Stop Condition-Street 1	StopSign					X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A					X Walk 1 Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	8.5	N/A	Storm Grate/Utility Hazard?	N/A
				N	Α	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N		Any Obstructions?	N/A			N/A
		Total Cost:	\$	1600.00	•	Obstruction Type		Yes	Surface Condition? (G/P)	Good
			Ŧ				N/A	N/A	Curb Slope (%)	13.1

