

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

49.5

35.0

11.7

3.2

6.4

8.6

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Main Street: FONTANA AV Intersection ID: 10198 **Cross Street: REMBERT CT** Location: NE Initial Pass/Fail: Fail **Overall Compliance: No** ADA ID: 98F766C02222 Ramp Type: Combination2 **Severity Score:** 72.5

**Codes/Mitigation Info/Possible Solution** 

**Field Measurements/Component Compliance** 

N/A

No

No

No

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Flare Type RT

Ramp XSlope RT (%)

Data

49.0

18.0

3.4

3.0

60.0

48.0

N/A

N/A

N/A

N/A

N/A

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)



Street 1 Name StopSign REMBERT CT Stop Condition-Street 1 Street 2 Name N/A Stop Condition-Street 2 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. N/A N/A N/A N/A Yes Surveyor Notes: N/A LT RP < 5% N/A N/A N/A N/A PROW/ADA: N/A Not Found, R304.5.1, R304.5.3, N/A R304.3.2 N/A N/A N/A N/A N/A





Total Cost:



N/A

1600.00

<b>0</b> 1 ( )				
Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Shared Landing?	N/A			
Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A
X Walk 1 X Slope (%)	3.5		X Walk 2 X Slope (%)	N/A
Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Road Slope (%)	N/A		Clear Space?	N/A
Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstruction?	N/A
			Obstruction Type	
				N/A
		N/A	Storm Grate/Utility Hazard?	N/A
			Storm Grate/Utility Type	
				N/A
		Yes	Surface Condition? (G/P)	Good
			Curb Slope (%)	16.5