## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 48943	43 Main Street: CALDWELL_RIDGE_PY			Cross Street: MORGAN_LEE_AV				Location:	<u>N</u>	
ADA ID: 99A7F048F5E5	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data		
		Remove & Replace Curb R	amp With	N/A	Ramp Length (in)	71.5	Yes	BlendTrans Slope (%)	3.9	
		Two New Directional Ramp	amps or	No	Ramp Width (in)	46.5	Yes	BlendTrans XSlope (%)	2.0	
E.		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
6. 6.		4		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
A CONTRACTOR		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
E EE		P		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
La Alexandre La				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
					X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name CAI	LDWELL RIDGE PY				X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	0.5		Clear Space?	N/A	
					Road X Slope (%)	1.8	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.0	0	Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

16.1