

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10123	Main Street: GLENWOOD_DR			ross Street:	TUCKASEEGEE_RD			Location:	SE
ADA ID: 99D8D87C6266	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compli			ance: No Severity Score:		25
С	odes/Mitigation Info	/Possible Solution			Field Measure	ements/C	ompo	nent Compliance	
	a land	Possible Solutions:		Compliance Description			Data Compliance Description		
	172	Remove & Replace Entire F	Ramp.	N/A	Ramp Length (in)	52.0	N/A	Grade Break?	N/A
				Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	A AR Have			No	Ramp Slope (%)	13.4	N/A	Grade Break XSlope (%)	0.0
E B B	No the Cal			Yes	Ramp XSlope (%)	1.5			
ITUM 6	I S MA			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A A A A A A A A A A A A A A A A A A A	1. 22 1			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
6	STEL DO	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
the second se	Ser 1	PONDING ON RAMP		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
AN PERMIT				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
182 182	-		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	The state of the s			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	W. W. St. C.	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
A ALAND		R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
		á l		N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
a print and the second	A The second second			N/A	Painted X Walk1?	Yes		Road Slope (%)	7.4
Street 1 Name	TUCKASEEGEE RD	-			X Walk 1 Direction	To N		Road X Slope (%)	0.9
Stop Condition-Street 1	Signal				X Walk 1 Width (in)	114.0		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	7.4	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.9	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost:	\$ 1600	0.00	Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	11.9

