

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

Intersection ID: 53349 Main Street: SAPPHIRE_HILL_LN Cross Street: N/A Location: SE

ADA ID: 9A1EE5C7FFF8 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Data Compliance Description



Street 1 Name

Stop Condition-Street 2

Street 2 Name

N/A

Stop Condition-Street 1

N/A

| 71 CCCIBIC CCIGNON | | i ioia iiio |
|-------------------------------|------|----------------------|
| Possible Solutions: | Comp | liance Description |
| Remove & Replace Entire Ramp. | N/A | Ramp Length (in) |
| | Yes | Ramp Width (in) |
| | N/A | Flare Type LT |
| | N/A | Flare Slope LT (%) |
| | N/A | Flare Traversable LT |
| | N/A | Landing Length (in) |
| Surveyor Notes: | N/A | Landing Width (in) |
| N/A | N/A | Landing Slope (%) |
| | N/A | Landing X Slope (%) |
| | N/A | Landing Curb? (Y/N) |
| | N/A | Shared Landing? |
| PROW/ADA: | N/A | Gutter Ponding? |
| Not Found, R304.5.3 | N/A | Gutter Lip Ht (in) |
| | N/A | Painted X Walk1? |
| | | X Walk 1 Direction |
| | N/A | X Walk 1 Width (in) |
| | | X Walk 1 Slope (%) |
| | | X Walk 1 X Slope (% |
| | N/A | Ramp inside XWalk1 |
| | | Road Slope (%) |

| Total Cost: | \$ 1850.00 |
|-------------|---------------|
| | |

| N/A | Ramp Length (in) | 47.5 | Yes | Ramp Slope (%) | 6.5 |
|-----|-----------------------|-------|-----|-----------------------------|------|
| Yes | Ramp Width (in) | 59.0 | No | Ramp XSlope (%) | 2.9 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NE | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.7 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 3.2 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | l | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | - Aller | | | | |





