cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



							Leastion	05	
Intersection ID: 10042268	2268 Main Street: WOODRIVER_LN		Cross	Cross Street: N/A				Location:	SE
ADA ID: 9A903E3C28A4	9A903E3C28A4 Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	THE REAL	Possible Solutions:		Compliance Description Data			Compliance Description		Data
		Remove & Replace Curb Ram	p With	N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	3.2
		Two New Directional Ramps o	, pr	No	Ramp Width (in)	46.0	Yes	BlendTrans XSlope (%)	1.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	CON			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
TIDODETVER				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
We		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The fat is a final state			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name WO	ODRIVER LN				X Walk 1 Slope (%)	0.7		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	1.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	1.2		Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

30.4