

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44475	475 Main Street: VALCOURT_RD			Cross Street: WESTHOPE_ST				Location:	SE
ADA ID: 9D3A4E96771D	Ramp Ty	Ramp Type: BlendTrans1			Initial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	COTTENT COOLINATION LIN	Possible Solutions:		Compliance Description			Data Compliance Description		Data
A REAL		Remove & Replace Curb Ran	np With	N/A	Ramp Length (in)	45.5	Yes	BlendTrans Slope (%)	4.1
		Two New Directional Ramps	•	No	Ramp Width (in)	47.0	No	BlendTrans XSlope (%)	3.0
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		LNDG GAP 1.0		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
Lo Houng				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	ANG.			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		1		N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
E. Koto	AL A.	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
the second secon				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To N		X Walk 2 Direction	To W
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	COREY COMMON AV	-			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	3.8
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	1.5
Street 2 Name	WESTHOPE ST			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	4.5		Clear Space?	N/A
					Road X Slope (%)	0.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
					••	N/A			N/A









Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.7