## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9624 Main Street: N_GREGG_ST Cross Street: SELDON_DR Location:								Е	
	Main Street: N_GREGG_ST				Location:				
ADA ID: 9D87B0BDF421 Ramp T	F421 Ramp Type: BlendTrans1		Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:	<u>c</u>	Compliance Description Data			Compliance Description		Data	
	Remove & Replace Curb Ramp \	Nith N	I/A	Ramp Length (in)	75.0	Yes	BlendTrans Slope (%)	3.3	
	Two New Directional Ramps o Equivalent.	Ν	lo	Ramp Width (in)	47.0	Yes	BlendTrans XSlope (%)	2.8	
		Ν	I/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
		Ν	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		Ν	I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		Ν	I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	Ν	I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	Ν	I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	5	N	I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N	I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N	I/A	Shared Landing?	N/A				
	PROW/ADA:	N	I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.1	N	I/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	·····, ·····	Ν	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name SELDON DR	_			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1 None				X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A		N	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2 N/A				Road Slope (%)	4.3		Clear Space?	N/A	
				Road X Slope (%)	0.9	N/A	Clear Space to XWalk (in)	N/A	
		Ν	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 33	200.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	





Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

9.2