

Intersection ID: 10041692	Main Street: WILBURN_CT	Cross Street: N/A	Location:	E
ADA ID: 9DE929DB07E4	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 21.25

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
<p>1. Code 100: No visible signs of corrosion or damage.</p> <p>2. Code 101: Minor surface corrosion, no structural impact.</p> <p>3. Code 102: Moderate surface corrosion, minor pitting.</p> <p>4. Code 103: Severe surface corrosion, significant pitting.</p> <p>5. Code 104: Corrosion with visible structural damage.</p> <p>6. Code 105: Corrosion with significant structural damage.</p> <p>7. Code 106: Corrosion with severe structural damage.</p> <p>8. Code 107: Corrosion with critical structural damage.</p> <p>9. Code 108: Corrosion with complete structural failure.</p>	<p>1. Field Measurements: Visual inspection, ultrasonic testing, etc.</p> <p>2. Component Compliance: Check against design specifications and standards.</p>



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	6.3		
	No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	5.2		
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
Surveyor Notes:	N/A	Shared Landing?	N/A					
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
		X Walk 1 Direction	To S		X Walk 2 Direction	N/A		
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
		X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	N/A		
		X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)	N/A		
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
		Road Slope (%)	N/A	N/A	Clear Space?	N/A		
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
Total Cost:	\$	1850.00	N/A					
		Obstruction Type			Storm Grate/Utility Hazard?	N/A		
					Storm Grate/Utility Type	N/A		
					Yes	Surface Condition? (G/P)	Good	

Total Cost: \$ 1850.00

