

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7129	Main Street: DAWNSHIRE_AV			Street:	NORTHBROOK_DR	Location:	NW			
ADA ID: 9E2E92D0F602	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
the state and	Contraction of the local division of the	Possible Solutions:	Compliance Description			Data	Data Compliance Description			
and the second second		Remove & Replace Entire Ramp		N/A	Ramp Length (in)	41.0	Yes	Ramp Slope (%)	5.5	
	AND THE PARTY OF			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	4.1	
	The second second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the part of the second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
* a	1 5			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
2	Stati La	N N		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second secon		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	The states of	2		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
S DIS	1 1 Maria			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
THEROO.	A Part to			N/A	Shared Landing?	N/A				
NOI3U	A Lock Markin	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
TH BE		·		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	and the				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
	11			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	NORTHBOOK DR				X Walk 1 Slope (%)	1.6		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	

Yes Surface Condition? (G/P)

Good

