cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 42582	582 Main Street: COLLEGE-TRYON_ST				Street:	N_TRYON_ST	Location:	S			
ADA ID: 9E9F1979260A					Initial Pass/Fail: Fail Overall Compliance: No					25	
· · · ·			IIIIIdi						25		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
	11 10 10 10	Possible Solutions:			Compliance Description			Data Compliance Description			
**********///	144 P	Remove & Replace En	tire Ram	р.	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	10.5	
5	A Que				Yes	Ramp Width (in)	60.0	No	Ramp XSlope (%)	6.0	
	SULLEGE				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6. 1	2 - 0 - 40				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
8/1	CARD -				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
Star Star	No. Vin				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	I HE TOBA	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
St St Contraction	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
A A A A A A A A A A A A A A A A A A A	No State				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
and the season	Alling How and a line				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	Not and a second				N/A	Shared Landing?	N/A				
11 - Sendare -	A Real Contraction	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
11 3 4 3 4 3 4 3 4	Not Found, R304.2.2, F	R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
A PARA S	- Instanting	, , ,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
A D A S A S A S						X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
Street 1 Name	COLLEGE-TRYON ST					X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	YieldSign					X Walk 1 X Slope (%)	7.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	

Yes Surface Condition? (G/P)

Good

