

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 3924Main Street: COPPERPLATE\_RDCross Street: WILBURN\_PARK\_CTLocation:NEADA ID: 9ED5701E6D77Ramp Type: Directional1Initial Pass/Fail: FailOverall Compliance: NoSeverity Score: 12.5

ADA ID: 9ED5701E6D77 Ramp Type: Directional1			Initial	Pass/F	ail: Fail Overall	Complian	ce: N	o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance									
		Possible Solutions:		Compliance Description		Data	Comp	ance Description	Data
ا		Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	100.0	N/A	Grade Break?	N/A
<mark> </mark>		-		Yes	Ramp Width (in)	96.0	N/A	Grade Break Slope (%)	0.0
ig i				Yes	Ramp Slope (%)	5.5	N/A	Grade Break XSlope (%)	0.0
				No	Ramp XSlope (%)	5.1			
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E E		CURB GAP 1.5"		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
<u> </u>	RPLATE_RD	1		N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
		PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	5.6
Street 1 Name	WILBURN PARK CT.				X Walk 1 Direction	To W		Road X Slope (%)	0.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	18.3





