cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



									/	
Intersection ID: 54324	Main Street: BELMONT_MANSION_DR			Cross Street: ROCKY_HILL_CASTLE_DR				Location:	SW	
ADA ID: A080DA69C6AE	Ramp Type: BlendTrans1			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Compliance Description					Data	
		Remove & Replace Curb Ram	n Mith	N/A	Ramp Length (in)	96.0	Yes	BlendTrans Slope (%)	1.3	
	Service Servic	Two New Directional Ramps o		Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	5.5	
		Equivalent.	•	N/A	Flare Type LT	-10.0 N/A		Flare Type RT	N/A	
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
				N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A	
	Y L			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
				N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A	
	<u>6</u>	N/A			0 . ()			0 ()		
ALL			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A		
					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
Street 1 Name BELMONT MANSION DR					X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 2	N/A				Road Slope (%)	4.3		Clear Space?	N/A	
					Road X Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
					,,	N/A			N/A	
							1			







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

6.3