

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

0.0

0.0

N/A

0.0

N/A

N/A

N/A

Intersection ID: 10030167 Main Street: LATROBE_DR Cross Street: N/A Location: NE

ADA ID: A0D8E359C930 Ramp Type: Directional1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 18.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Grade Break?

Flare Type RT

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

Flare Traversable RT?

Grade Break Slope (%)

Grade Break XSlope (%)

Data

48.0

32.0

3.9

3.7

N/A

N/A

N/A

0.0

0.0



Street 1 Name	ENTRANCE
Stop Condition-Street 1	None
Street 2 Name	N/A
Stop Condition-Street 2	N/A

Possible Solutions:	Comp	liance Description		
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)		
•	No	Ramp Width (in)		
	Yes	Ramp Slope (%)		
	Yes	Ramp XSlope (%)		
	N/A	Flare Type LT		
	N/A	Flare Slope LT (%)		
Surveyor Notes:	N/A	Flare Traversable LT?		
N/A	N/A	Landing Length (in)		
	N/A	Landing Width (in)		
	N/A	Landing Slope (%)		
	N/A	Landing X Slope (%)		
PROW/ADA:	N/A	Landing Curb? (Y/N)		
R304.5.1	N/A	Shared Landing?		
	N/A	Gutter Ponding?		
	N/A	Gutter Lip Ht (in)		
	N/A	Painted X Walk1?		
		X Walk 1 Direction		
		X Walk 1 Width (in)		
		X Walk 1 Slope (%)		
		X Walk 1 X Slope (%)		

iotai oost.				
		0.0	100	600
8 1		THE	D CERSON TON	
- ATTEMENT	C 24	S	C/	2
			-	
				4

Total Cost:





Landing Slope (%) 0.0 N/A DWS Length (in) N/A 0.0 N/A DWS Full Width? Landing X Slope (%) N/A Landing Curb? (Y/N) N/A N/A DWS Offset LT (in) N/A Shared Landing? N/A N/A DWS Offset RT (in) N/A **Gutter Ponding?** 0.0 N/A Gutter Slope (%) N/A Gutter Lip Ht (in) 4.0 N/A Gutter X Slope (%) N/A Painted X Walk1? No Road Slope (%) 5.6 To SE X Walk 1 Direction Road X Slope (%) 6.3 X Walk 1 Width (in) N/A Clear Space? N/A X Walk 1 Slope (%) 5.6 N/A Clear Space to XWalk (in) N/A X Walk 1 X Slope (%) 6.3 N/A Storm Grate/Utility Hazard? N/A N/A Ramp inside XWalk1? N/A Storm Grate/Utility Type Any Obstructions? N/A N/A N/A **Obstruction Type** Surface Condition? (G/P) 1600.00 Yes Good N/A N/A Curb Slope (%) 3.9