

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 11796 Main Street: N\_PINE\_ST Cross Street: W\_6TH\_ST Location: E

ADA ID: A1A6A90A02D9 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

9 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score:

Codes/Mitigation Info/Possible Solution Field Measurements/Component Compliance

## Codes/Mitigation Info/P

The second secon	NAME OF TAXABLE PARTY.
Street 1 Name	N PINE ST
Stop Condition-Street 2	Signal
Street 2 Name	W 6TH ST
Stop Condition-Street 1	Signal

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Date Compliance Description Date							
	npliance Description	Data		pliance Description	Data		
N/A	1 3 ( )	50.0	No	Ramp Slope (%)	15.1		
Yes	1 ( )	78.0	No	Ramp XSlope (%)	6.6		
N/A	71	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes		
	X Walk 1 Direction	To NW		X Walk 2 Direction	To SW		
N/A	X Walk 1 Width (in)	117.0	N/A	X Walk 2 Width (in)	100.0		
	X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	6.0		
	X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	1.2		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes		
	Road Slope (%)	5.4	N/A	Clear Space?	N/A		
	Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
-37	Market I was to see	,	-	• •			





