cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



· · · ·										
Intersection ID: 10023269 Main Street: CHELTON_RIDGE_LN				Cross	Street:	N/A	Location:	NE		
ADA ID: A27EEA79ED06 Ramp Type: BlendTrans1					Pass/Fa	ail: Fail Overall	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
	DESTIN_LIN 6	Possible Solutions:			Compliance Description Data C			Comp	Compliance Description	
		Remove & Replace Curb Ra Two New Directional Ramps Equivalent.	Ram	p With	N/A	Ramp Length (in)	53.0	Yes	BlendTrans Slope (%)	4.8
					No	Ramp Width (in)	45.0	No	BlendTrans XSlope (%)	2.3
			•		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
S (1)	1 - Parts	Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	LET TOWN	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and an instance for the				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
and the second sec					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A				
	17 Maria	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Section	R304.5.1, R304.5.3			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
						X Walk 1 Direction	To NW		X Walk 2 Direction	To S
						X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	CHELTON RIDGE LN					X Walk 1 Slope (%)	1.8		X Walk 2 Slope (%)	0.2
Stop Condition-Street 1	None					X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	0.7
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None					Road Slope (%)	0.4		Clear Space?	N/A
						Road X Slope (%)	2.4	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A







Yes

N/A

Surface Condition? (G/P)

Curb Slope (%)

Good

3.8