

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14281	Main Str	Crose	Cross Street: LYNDHURST_AV				Location:	W		
		Main Street: E_KINGSTON_AV								
ADA ID: A2C513B79119 Ramp Type: Directional1		Initial P	Initial Pass/Fail: Fail Overall Compliance: N			nce: N	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
		Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram) .	N/A	Ramp Length (in)	64.0	N/A	Grade Break?	N/A	
	AT ST 1			Yes	Ramp Width (in)	58.0	N/A	Grade Break Slope (%)	0.0	
	3 10			Yes	Ramp Slope (%)	5.9	N/A	Grade Break XSlope (%)	0.0	
A HOLE W C.	7/ / N/			No	Ramp XSlope (%)	5.1				
	1 1 11			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	h Stille D			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
<u>E</u> X	5. A 2 - /	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
5.	B. M. S			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
La balance	19 31			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
STATE OF STATE	A Carille			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
PROW/ADA:				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	the secto	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	Con the second			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	Y. ADA G			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
R. M. Martin	- LANCA			N/A	Painted X Walk1?	No		Road Slope (%)	7.5	
Street 1 Name	E KINGSTON AV				X Walk 1 Direction	To NE		Road X Slope (%)	1.9	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	7.5	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.9	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	0.2	

