

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

11.0

0.4

N/A

N/A

N/A

Intersection ID: N/A Main Street: COPPER WY **Cross Street: N/A** Location: NW **Overall Compliance: No** ADA ID: A3AA02B8A306 Ramp Type: Perp Initial Pass/Fail: Fail **Severity Score:** 12.5

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

Flare Traversable RT?

Flare Type RT

Data

199.0

48.0

N/A

N/A



19 10 10 10 10 10 10 10 10 10 10 10 10 10	
Street 1 Name	COPPER WY
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

"	1 Cocibio Colditoli
į	Possible Solutions:
	Remove & Replace Entire Ramp.
100	
1	
100	Surveyor Notes:
	N/A
Š	PROW/ADA:
J	Not Found
7	
_	

Vina Chicken To Go
• A



A HI SA					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
E E		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	100	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	5				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
0					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
6					N/A	Shared Landing?	N/A				
		PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		Not Found			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	1				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
						X Walk 1 Direction	To SE		X Walk 2 Direction	N/A	
					N/A	X Walk 1 Width (in)	101.0	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	COPPER WY					X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost:	\$	1850.00		Obstruction Type			Storm Grate/Utility Type		
							N/A			N/A	
								Yes	Surface Condition? (G/P)	Good	
	7	Vica che or To Co	in h			Beauty !					