

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10025398 Main Str	Main Street: E_ARROWOOD_RD		Cross Street: S_OAK_MARKETPLACE_DR				Location:	SW	
ADA ID: A44D1E2F21EB Ramp Type: Directional1		Initial Pa	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description			Data Compliance Description			
	Remove & Replace Entire Ram	D .	N/A	Ramp Length (in)	87.0	N/A	Grade Break?	N/A	
	· · · · · · · · · · · · · · · · · · ·	•	Yes	Ramp Width (in)	90.0	N/A	Grade Break Slope (%)	0.0	
And an area of the second			No	Ramp Slope (%)	12.6	N/A	Grade Break XSlope (%)	0.0	
			Yes	Ramp XSlope (%)	0.5				
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
E ARROWOOD RD			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the test of the second se	LOCATED ON MEDIAN		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
A REAL PROPERTY AND A REAL PROPERTY AND			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
E In C IA			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
Contraction of the Contraction	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	Yes		Road Slope (%)	6.4	
Street 1 Name S OAK MARKETPLACE DR	_			X Walk 1 Direction	To W		Road X Slope (%)	2.3	
Stop Condition-Street 1 StopSign				X Walk 1 Width (in)	121.0		Clear Space?	N/A	
Street 2 Name N/A				X Walk 1 Slope (%)	6.4	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2 N/A				X Walk 1 X Slope (%)	2.3	N/A	Storm Grate/Utility Hazard?	N/A	
			N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
			N/A	Any Obstructions?	N/A			N/A	
	Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
					N/A	N/A	Curb Slope (%)	12.4	

