cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 47581 Main	section ID: 47581 Main Street: ROCK_ISLAND_RD		Cross Street: GLENBURN_LN			Location:	NE	
ADA ID: A46577EBA475 Ramp Type: PerpDiag		Initial Pass/F	itial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:	Com	Compliance Description Data		Compliance Description		Data	
	Remove & Replace Curb Ramp Wit	th N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	8.8	
	Two New Directional Ramps or Equivalent.	Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.7	
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	5 b	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
		N/A	Shared Landing?	N/A				
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
	200	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name GLENBURN L	 N		X Walk 1 Slope (%)	2.9		X Walk 2 Slope (%)	2.4	
Stop Condition-Street 2 StopSig	n		X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	2.4	
Street 2 Name ROCK ISLAND R	D	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 Nor	e		Road Slope (%)	2.6	N/A	Clear Space?	N/A	
			Road X Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A	
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$ 320	00.00	Obstruction Type			Storm Grate/Utility Type		
				N/A			N/A	

