

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49932	Main Str	Main Street: WOBURN_RD				PAXTON_RUN_RD	Location:	NE		
ADA ID: A4F9AA5CBBFB	Ramp Ty	Ramp Type: Perp			s/Fa	il: Fail Overall (o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:									liance Description	Data
	4 6 6		Entiro Domo			Ramp Length (in)	46.0	Yes	Ramp Slope (%)	6.8
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Remove & Replace	Entire Ramp.	N		Ramp Width (in)	46.0	No	Ramp XSlope (%)	4.8
				N/		Flare Type LT	40.0 N/A	N/A	Flare Type RT	4.0 N/A
	AL AN			N/		Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
	AL OP					,			,	
		1		N/		Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/		Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/		Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		N/A		N/		Landing Slope (%)	N/A		DWS Length (in)	N/A
				N/	/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
EUGULA IS				N/	/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Moe dia				N/	/A	Shared Landing?	N/A			
		PROW/ADA:		N/	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
A REAL PROPERTY AND A REAL	1 3	Not Found, R304.5	.1. R304.5.3	N/	Ά	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
a second a second	I TOTAL		,	N/	/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
						X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
				N	/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	PAXTON RUN RD	•				X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	2.2		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N	Δ/	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
	N/A					,	N/A	N/A	Clear Space to XWalk (in)	N/A
				N	/ A	Road X Slope (%)	N/A	N/A		N/A N/A
		Tatal Cast	* 4		A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

