cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15072	Main Street: DILWORTH_RD_EAST			Cross Street: E WORTHINGTON AV				Location: E	
ADA ID: A5E7702FD464	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliand			o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
And And		Possible Solutions:					a Compliance Description Data		
	et :	Remove & Replace Entire Ram	מו.	N/A	Ramp Length (in)	108.0	N/A	Grade Break?	N/A
	1 2 2 2	·····		Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
	1 2 2 2			No	Ramp Slope (%)	10.3	N/A	Grade Break XSlope (%)	0.0
	Like I			No	Ramp XSlope (%)	3.6			
B/				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the second s				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
6 6 8	THAN SOME	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E E	A AN	RAMP LIP 1.0"		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
the second second	A CAR COM			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
L. C. C.	The second second			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	A LOSA	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
The sa	A NOR POR	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	Contraction of the second	,		N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
	and with the state			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
	A Company of the			N/A	Painted X Walk1?	No		Road Slope (%)	4.8
Street 1 Name	DILWORTH RD EAST				X Walk 1 Direction	To NW		Road X Slope (%)	0.2
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	4.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.2	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	7.5

