

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54423	tersection ID: 54423 Main Street: BLARNEY_RIDGE_DR			Cross Street: KILKENNY_DR				Location:	N
ADA ID: A664A28E368F	A664A28E368F Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description Data Co			Comp	Compliance Description Data	
		Remove & Replace Entire Ra	mp.	N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A
	City in the second			Yes	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	0.0
A CARLON	1911	1		Yes	Ramp Slope (%)	7.1	N/A	Grade Break XSlope (%)	0.0
A Real Provide State				No	Ramp XSlope (%)	4.5			
	1/10/1			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	A Start			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
	<b>B</b>	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E.	K.	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
	1122 113			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	1 Serless			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
A THE	AND LADES			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	27	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	All Martin Star	R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
Sale of the second				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
2 1/ /	1/ 2 / 1 / 2 Mal			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No		Road Slope (%)	4.1
Street 1 Name	BLARNEY RIDGE DR				X Walk 1 Direction	To SW		Road X Slope (%)	4.4
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.4	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	4.3

