

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 12850	Main Stre	eet: CONNELLY_CR	Cross Street: MORRIS_FIELD_DR			Location:	SW		
ADA ID: A6708C6059C8	Ramp Ty	/pe: Directional1	Initial Pass/Fail: Fail Overall Compliance: No			o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:				ta Compliance Description		Data	
	A A A	Remove & Replace Entire Ramp	. N/A	Ramp Length (in)	30.0	N/A	Grade Break?	N/A	
	SFE WHE	······	Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0	
	· A · S · A · A ·		Yes	Ramp Slope (%)	2.4	N/A	Grade Break XSlope (%)	0.0	
	AL.		No	Ramp XSlope (%)	6.1		• • •		
A A A A A A A A A A A A A A A A A A A	11713		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
Barrier Ba	8		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	ST I I	Surveyor Notes:	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the state of the s		N/A	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
8	and.		N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
A A A A A A A A A A A A A A A A A A A			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
a lateral 1/1	File	PROW/ADA:	N/A	Landing Curb? (Y/N)	N/A		DWS Offset LT (in)	N/A	
	Contraction of the	R304.5.3	N/A	Shared Landing?	N/A		DWS Offset RT (in)	N/A	
		1004.0.0	N/A	Gutter Ponding?	0.0		Gutter Slope (%)	N/A	
	Contraction of the second seco		N/A	Gutter Lip Ht (in)	0.0		Gutter X Slope (%)	N/A	
1 the form	and a		N/A	Painted X Walk1?	No		Road Slope (%)	1.2	
Street 1 Name	CONNELLY CR	1		X Walk 1 Direction	To N		Road X Slope (%)	7.4	
Stop Condition-Street 1	StopSign			X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A			X Walk 1 Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A			X Walk 1 X Slope (%)	7.4	N/A	Storm Grate/Utility Hazard?	N/A	
••••F			N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
			N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
		•••••••••••••••••••••••••••••••••••••••			N/A	N/A	Curb Slope (%)	7.0	
1					0/4				

