

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street:LANGWELL_LNCross Street:INVERNESS_BAY_RDLocation:NWADA ID: A6B35A02739ERamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution



Street 1 Name

Stop Condition-Street 2

Street 2 Name

N/A

Stop Condition-Street 1

N/A

| Possible Solutions: |
|-------------------------------|
| Remove & Replace Entire Ramp. |
| |
| |
| |
| |
| |
| Surveyor Notes: |
| N/A |
| |
| |
| |
| PROW/ADA: |
| R304.5.3 |
| 1004.0.0 |
| |
| |
| |
| |
| |
| |
| |
| |

| Z | |
|---|--|
| | |
| A | |
| | |



Total Cost:



1850.00

| Field Measurements/Component Compliance | | | | | | | |
|---|---|-------|------|-----------------------------|------|--|--|
| Comp | liance Description | Data | Comp | liance Description | Data | | |
| N/A | Ramp Length (in) | 47.0 | Yes | Ramp Slope (%) | 7.3 | | |
| Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 6.6 | | |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | | |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | | |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | | |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | | |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | | |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | | |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | | |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | | |
| N/A | Shared Landing? | N/A | | | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | | |
| N/A | Gutter Lip Ht (in) | 1.0 | N/A | Gutter X Slope (%) | N/A | | |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | | |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A | | |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | | |
| | X Walk 1 Slope (%) | 3.5 | | X Walk 2 Slope (%) | N/A | | |
| | X Walk 1 X Slope (%) | 2.8 | | X Walk 2 X Slope (%) | N/A | | |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | | |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A | | |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | | |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | | |
| | Obstruction Type | | | Storm Grate/Utility Type | | | |
| | | N/A | | | N/A | | |
| | | | Yes | Surface Condition? (G/P) | Good | | |
| | Photo Control of the | | | | | | |