

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

48.0

59.5

8.4

0.5

3.1

7.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 11085 Main Street: GLENVILLE_AV Cross Street: PURSER_DR Location: SE

ADA ID: A7B1B383DBE0 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 37.5

Compliance Description

N/A

Yes

No

Yes

N/A

Yes

N/A

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp XSlope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

Yes

No

Yes

Yes

No

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Data

54.0

60.0

9.8

1.4

24.5

48.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
StopSign
Stop Condition-Street 1
PURSER DR
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.3.2



Total Cost:



1800.00

Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk2? Painted X Walk1? No N/A To N X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A 1.9 N/A X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.3 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 8.4 Curb Slope (%)