cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10396 Main Street: DADE ST Cross Street: THE PLAZA Location: S									
Intersection ID: 10396	Main St	Main Street: DADE_ST			Cross Street: THE_PLAZA				S
ADA ID: A7B7514F72C4	Ramp T	ype: BlendTrans1	In	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	1 23	Possible Solutions:	Comp	Compliance Description			Data Compliance Description		
		Remove & Replace Curb F	Ramp With	N/A	Ramp Length (in)	55.5	Yes	BlendTrans Slope (%)	0.0
		Two New Directional Ram		No	Ramp Width (in)	36.5	No	BlendTrans XSlope (%)	2.8
		Equivalent.	-	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
13	1750	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1 Kin	NO RT SW		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
of the second		Not Found, R304.5.1, R30	4.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
		,,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
LANGER MAL		r			X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	DADE ST	_			X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	4.3		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	4.3		Clear Space?	N/A
					Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 3200.0	0	Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

14.5