

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.0

0.3

N/A

Good

Intersection ID: 12446 Main Street: ASHLAND AV **Cross Street: BELVEDERE AV** Location: SW ADA ID: A826D0BFD20D Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 8.75 **Severity Score:**

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

Flare Traversable RT?

Flare Type RT

Data

97.0

47.0

N/A

N/A

N/A

N/A


N/A



	A CHARLES
Street 1 Name	ASHLAND AV
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:				
Remove & Replace Entire Ramp.				
Surveyor Notes:				
N/A				
PROW/ADA:				
R304.5.1				

Total Cost:	\$	1850.00



N/A

No

N/A

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Type LT

ling X Slope (%)	N/A	N/A	DWS Full Width?
ling Curb? (Y/N)	N/A	N/A	DWS Offset (in)
ed Landing?	N/A		
er Ponding?	N/A	N/A	Gutter Slope (%)
er Lip Ht (in)	N/A	N/A	Gutter X Slope (%)
ted X Walk1?	No	N/A	Painted X Walk2?
alk 1 Direction	To E		X Walk 2 Direction
alk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)
alk 1 Slope (%)	1.3		X Walk 2 Slope (%)
alk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)
p inside XWalk1?	N/A	N/A	Ramp inside XWalk2?
d Slope (%)	N/A	N/A	Clear Space?
d X Slope (%)	N/A	N/A	Clear Space to XWalk (in)
Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?
truction Type		l	Storm Grate/Utility Type
	N/A		
		Yes	Surface Condition? (G/P)





