

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25405Main Street:MARMOT\_POINT\_LNCross Street:PROVIDENCE\_PLANTATION\_LNLocation:NEADA ID: A93C05CCE6BERamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:36.25

**Codes/Mitigation Info/Possible Solution** 

Total Cost:

## Field Measurements/Component Compliance



Street 1 Name	MARMOT POINT LN
Stop Condition-Street 2	StopSign
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Possible Solutions:
Remove & Replace Entire Ramp.
Surveyor Notes:
N/A
PROW/ADA:
Not Found, R304.5.1, R304.5.3
, , , , , , , , , , , , , , , , , , , ,

			arc. 4
		-	



1850.00

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	96.0	Yes	Ramp	Slope (%)	7.8
No	Ramp Width (in)	29.0	No	Ramp	XSlope (%)	4.7
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	N/A
	X Walk 1 Direction	To W		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.0		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	3.3		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good