

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.0

24.0

6.2

0.2

5.1

8.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Intersection ID: 6102 Main Street: UNIVERSITY\_CITY\_BV Cross Street: UNIVERSITY\_PROFESSIONAL\_DR Location: SE

ADA ID: AA6B062DF31B Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 47.5

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Flare Traversable LT?

Flare Type LT

Ramp XSlope LT (%)

N/A

No

No

Yes

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

No

Yes

Yes

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

Flare Traversable RT?

Data

67.0

24.0

8.4

2.0

36.0

43.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name
Signal
Stop Condition-Street 1
CAERON BV
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.3.2



Total Cost:



1800.00

Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? Yes Painted X Walk2? N/A To E X Walk 1 Direction X Walk 2 Direction N/A X Walk 1 Width (in) 115.0 X Walk 2 Width (in) N/A 2.9 N/A X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 0.3 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? Yes N/A Ramp inside XWalk2? N/A Road Slope (%) N/A Clear Space? N/A Road X Slope (%) N/A N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 19.7 Curb Slope (%)

