

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/AMain Street:LANGWELL_LNCross Street:INVERNESS_BAY_RDLocation:NWADA ID: AB5E3CA4B07ARamp Type:PerpInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:33.75

Codes/Mitigation Info/Possible Solution



Street 1 Name INVERNESS BAY RD
Stop Condition-Street 2 StopSign
Street 2 Name N/A
Stop Condition-Street 1 N/A

Possible Solution	
Possible Solutions:	Comp
Remove & Replace Entire Ramp.	N/A
•	No
	N/A
	N/A
	N/A
	N/A
Surveyor Notes:	N/A
N/A	N/A
	N/A
	N/A
	N/A
PROW/ADA:	N/A
R304.5.1, R304.5.3	N/A
	N/A
	N/A
	N/A





Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Comp	liance	Description	Data	
N/A	Ramp Length (in)	46.5	Yes	Ramp	Slope (%)	7.0	
No	Ramp Width (in)	46.0	No	Ramp	XSlope (%)	8.7	
N/A	Flare Type LT	N/A	N/A	Flare	Гуре RT	N/A	
N/A	Flare Slope LT (%)	N/A	N/A	Flare S	Slope RT (%)	N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A	
N/A	Landing Length (in)	N/A	N/A	DWS I	Provided?	N/A	
N/A	Landing Width (in)	N/A	N/A	DWS (Contrast?	N/A	
N/A	Landing Slope (%)	N/A	N/A	DWS I	_ength (in)	N/A	
N/A	Landing X Slope (%)	N/A	N/A	DWS I	Full Width?	N/A	
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS (Offset (in)	N/A	
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter	Slope (%)	N/A	
N/A	Gutter Lip Ht (in)	1.0	N/A	Gutter	X Slope (%)	N/A	
N/A	Painted X Walk1?	No	N/A	Painte	d X Walk2?	N/A	
	X Walk 1 Direction	To SE		X Wall	c 2 Direction	N/A	
N/A	X Walk 1 Width (in)	N/A	N/A	X Wall	c 2 Width (in)	N/A	
	X Walk 1 Slope (%)	0.8		X Wall	< 2 Slope (%)	N/A	
	X Walk 1 X Slope (%)	6.3		X Wall	< 2 X Slope (%)	N/A	
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A	
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A	
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A	
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm	Grate/Utility Type		
		N/A				N/A	
			Yes	Surfac	e Condition? (G/P)	Good	